

**Schenevus Central School District
Lead Testing Results Summary & Remediation Plan**

| Outlet Location | Test Results 9.15.16 1st Draw | Test Results 10.12.16 1st Draw | Test Results 10.12.16 2nd Draw | Test Results 1.10.17 1st Draw | Test Results 5.31.17 1st Draw | Remediation Plan |
|---|---|--|--|---|---|--|
| 2 nd Floor Original Building Drinking Fountain (East) | 86.0 ppb | 25.9 ppb | 5.3 ppb | Removed | | This outlet has been removed. |
| 1 st Floor Main Office Bathroom Faucet | 17.0 ppb | 5.5 ppb | < 1 ppb | | | This outlet has been replaced with a new faucet, new shut off valve, and new supply line and placed back in service. |
| 1 st Floor Kitchen Sprayer | 1200.0 ppb | 20.1 ppb | < 1 ppb | 1.9 ppb | | This outlet has been replaced with a new sprayer and placed back in service. |
| 1 st Floor Kitchen Sink Left Faucet | 82.0 ppb | 24.0 ppb | 1.8 ppb | 6.6 ppb | | This outlet has been replaced with a new faucet and placed back in service. |
| 1 st Floor Original Building Drinking Fountain (West) | 18.0 ppb | 4.7 ppb | < 1 ppb | Removed | | This outlet has been removed. |
| 1 st Floor Room 114 Bathroom Faucet | 29.0 ppb | 4.3 ppb | 1.6 ppb | | | This outlet has been replaced with a new faucet and placed back in service. |
| 1 st Floor MS Girls Bathroom Center Faucet | 28.0 ppb | 30.6 ppb | 4.1 ppb | 18 ppb | < 1 ppb | This outlet has been replaced with a new faucet, new shut off valve, and new supply line and placed back in service. |
| Basement Computer Lab Drinking Fountain | 86.0 ppb | 43.6 ppb | 25.9 ppb | Removed | | This outlet and connected supply line has been removed. |
| Basement Room B04 Drinking Fountain | 93.0 ppb | 59.3 ppb | 8.1 ppb | Removed | | This outlet has been removed. |

Sampling conducted by Josh Reiss-ONC BOCES and Joseph Bomba-SCSD. Analysis conducted by Microbac Laboratories. Actionable level >15 ppb.